

| |
|--|
| |
| |



**MISSING ROOF-WALL DIVERTER FLASHING.
NOTE CRACK IN STUCCO.**



**IMPROPER AND UNSIGHTLY INSTALLATION OF
ROOF-WALL DIVERTER FLASHING POSTAFTER CONSTRUCTION.**