



REAR ELEVATION MULTIPLE WINDOW INSTALLATION.



CLOSE-UP OF CRACKING PATTERN FROM WINDOWS TO EDGE OF STRUCTURE.